

# WELDING & FORMING GUIDELINES

## GUIDELINES FOR SUPER-C® CLADDED WEAR PLATE

### Cutting Examples

Plasma arc cutting with conventional arc cutting techniques and gases are recommended for shape cutting, piercing large holes, and beveling.

### Grinding

Grinding and EDM methods are the only proven, satisfactory methods for precision removal of metal. When grinding a hard-grit, a soft bond wheel is required. For non-precision metal removal and hole piercing, use carbon arc gouging.

### Cold Forming

Generally, the power required to form Super-C™ will be approximately the same as required for low carbon.

### Welding

Super-C™ is normally supplied with plasma arc cut edges ready for welding. Welding to carbon steel support structures is accomplished with either Prime-Arc 85™ or Tri-Weld 3™ electrodes using the proper welding procedures. Care should be taken to prevent the clad portion of the plate from diluting the fillet weld.

#### 1-Layer


Nominal Thickness		Cladding Thickness*		Base Plate Thickness	
mm	inch	mm	inch	mm	inch
9,53	3/8	4,76	3/16	4,76	3/16
12,70	1/2	6,35	1/4	6,35	1/4
15,88	5/8	6,35	1/4	9,53	3/8
19,05	3/4	6,35	1/4	15,88	5/8
22,23	7/8	6,35	1/4	15,88	5/8
25,40	1	6,35	1/4	19,05	3/4

#### 2-Layer


Nominal Thickness		Cladding Thickness*		Base Plate Thickness	
mm	inch	mm	inch	mm	inch
12,70	1/2	7,94	5/16	6,35	1/4
15,88	5/8	9,53	3/8	6,35	1/4
19,05	3/4	9,53	3/8	9,53	3/8
22,23	7/8	9,53	3/8	12,70	1/2
25,40	1	9,53	3/8	15,88	5/8

### Examples:


#### FILLET WELDING



#### PLUG WELDING



#### SEAM WELDING



 **Super-C®**